ARISH BABU R.R. M.Sc.,

Jalashakthi Ground Water & Borewell Consultant

35/6, Kiran Complex, Opp. Mangalore Independent College,
Ullala Main Road, Muneshwara Nagar, Jnanabharathi Post,
Bangalore - 560 056.

Mobile : 99801 94377
98443 72004
E-mail : arishbabu11@gmail.com

GROUND WATER INVESTIGATION / ~~YIELD~~ REPORT

No.: KA 15/ 18-1120/01

Date : 20/11/2018

Name & Adress : To, AEE, Bagalagunte (Sub-Division), Banglore BBMP.

Purpose of Ground Water : Drinking water (Domestic)

Ground Water Potential : Good

Site Location : M.T.S. Colony (near Muthuraya Swamy Temple) ward # 15

Topography : Slope Terrian

Soil : Brownish Red

Rock below the soil : Granitic Gneiss

Water Striking Levels					
	1st Source	2nd Source	3rd Source	Casing	Yield
Point #(1)	450-470 Ft.	810-830 Ft.	970-990 Ft.	170-180 Ft.	2310/2500 Gals/Hr.
Point # 2	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 3	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 4	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 5	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 6	Ft.	Ft.	Ft.	Ft.	Gals/Hr.

Note : Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

(ARISH BABU R.R.)
Consultant Geologist / Diviner

Scanned by CamScanner

ARISH BABU R.R. M.Sc.,

Jalashakthi Ground Water & Borewell Consultant

35/6, Kiran Complex, Opp. Mangalore Independent College,
Ullala Main Road, Muneshwara Nagar, Jnanabharathi Post,
Bangalore - 560 056.

Mobile : 99801 94377
98443 72004
E-mail : arishbabu11@gmail.com

GROUND WATER INVESTIGATION / ~~YIELD~~ REPORT

No.: KAIS/18-1120/02 Date : 20/11/2018

Name & Adress : A.E.E. Bagalagunte (Sub Dilling) Dasarahalli, BBMP. Bangalore

Purpose of Ground Water : Domestic (Drinking water)

Ground Water Potential : Good

Site Location : Maheshwari Nagar, 6th B Cross (Near Muneshwara Temple)

Topography : Plain Terrain Ward # 15

Soil : Brownish Red

Rock below the soil : Granite Gneiss

Water Striking Levels

	1st Source	2nd Source	3rd Source	Casing	Yield
Point # 1	460-480 Ft.	710-730 Ft.	920-940 Ft.	150-160 Ft.	2200/2400 Gals/Hr.
Point # 2	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 3	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 4	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 5	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 6	Ft.	Ft.	Ft.	Ft.	Gals/Hr.

Note : Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure.

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

(ARISH BABU R.R.)
Consultant Geologist / Diviner

Scanned by CamScanner

ARISH BABU R.R. M.Sc.,

Jalashakthi Ground Water & Borewell Consultant

35/6, Kiran Complex, Opp. Mangalore Independent College,
Ullala Main Road, Muneshwara Nagar, Jnanabharathi Post,
Bangalore - 560 056.

Mobile : 99801 94377
98443 72004
E-mail : arishbabu11@gmail.com

GROUND WATER INVESTIGATION / ~~YIELD~~ REPORT

No.: KAIS/18-1122/03 Date : 20/11/2018

Name & Adress : To, AEE, Bagalagunte Sub Division, BBMP, Dasarahalli, Bangalore

Purpose of Ground Water : Drinking water (Domestic)

Ground Water Potential : Very Good

Site Location : Bhuvaneshwari Nagar (Behind Shiva Temple) ward # 15

Topography : Plain Terrain

Soil : Brown

Rock below the soil : Granitic Schist

Water Striking Levels					
	1st Source	2nd Source	3rd Source	Casing	Yield
Point # 1	510-530 Ft.	780-810 Ft.	910-930 Ft.	150-170 Ft.	2200/2000 Gals/Hr.
Point # 2	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 3	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 4	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 5	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 6	Ft.	Ft.	Ft.	Ft.	Gals/Hr.

Note : Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

(ARISH BABU R.R.)
Consultant Geologist / Diviner

Scanned by CamScanner

ARISH BABU R.R. M.Sc.,

Jalashakthi Ground Water & Borewell Consultant

35/6, Kiran Complex, Opp. Mangalore Independent College,
Ullala Main Road, Muneshwara Nagar, Jnanabharathi Post,
Bangalore - 560 056.

Mobile : 99801 94377
98443 72004
E-mail : arishbabu11@gmail.com

GROUND WATER INVESTIGATION / ~~YIELD~~ REPORT

No.: KA15/18-1122/024 Date 20/11/2018

Name & Adress : PO, AEE, Bagalgunte (Sub Division) BBMP, Dasarahalli Bangalore

Purpose of Ground Water : Domestic (Drinking water)

Ground Water Potential : Very Good

Site Location : Kempe Gowda Nagar (Near old Petrol Bunk Road) Ward #15

Topography : Plain Terrain

Soil : Brown

Rock below the soil : Granitic Gneiss

Water Striking Levels					
	1st Source	2nd Source	3rd Source	Casing	Yield
Point # 1	410-430 Ft.	690-710 Ft.	940-960 Ft.	140-170 Ft.	2210/2400 Gals/Hr.
Point # 2	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 3	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 4	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 5	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 6	Ft.	Ft.	Ft.	Ft.	Gals/Hr.

Note : Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure.

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಬಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

(ARISH BABU R.R.)
Consultant Geologist / Diviner

Scanned by CamScanner

ARISH BABU R.R. M.Sc.,

Jalashakthi Ground Water & Borewell Consultant

35/6, Kiran Complex, Opp. Mangalore Independent College,
Ullala Main Road, Muneshwara Nagar, Jnanabharathi Post,
Bangalore - 560 056.

Mobile : 99801 94377
98443 72004
E-mail : arishbabu11@gmail.com

GROUND WATER INVESTIGATION / ~~YIELD~~ REPORT

No.: KA 15 / 18-1122/05 Date : 20/11/2018

Name & Adress : To, ABB, Bagalagunte (Sub Divn), BBMP, Bangalore

Purpose of Ground Water : Domestic (Drinking water)

Ground Water Potential : Good

Site Location : Kempe Gowda Nagar 1st Main Road [Near Storm water Drain] ward #15

Topography : Plain Terrain

Soil : Brownish Red

Rock below the soil : Granite Gneiss

Water Striking Levels					
	1st Source	2nd Source	3rd Source	Casing	Yield
Point # (1)	410-430 Ft.	590-610 Ft.	920-940 Ft.	160-180 Ft.	2400/2600 Gals/Hr.
Point # 2	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 3	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 4	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 5	Ft.	Ft.	Ft.	Ft.	Gals/Hr.
Point # 6	Ft.	Ft.	Ft.	Ft.	Gals/Hr.

Note : Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಡಿ.ಎ.ಸಹಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

(ARISH BABU R.R.)
Consultant Geologist / Diviner

Scanned by CamScanner